

Suzuki SX4 S-Cross 1.4B COMFORT+ 2X4 / DAMAGED CAR

Reference	9086
Displacement	1373 cc
Power	103 kw/140 hp
CO2-emission	147 g/km (WLTP)
Euronorm	Euro 6d-Temp
Bodytype	SUV/4x4
State	2nd hand
1st registration	07/2020
Mileage	101750 km
Fuel	Gasoline
Color	Grey
Interior	Black Leather



Options

ABS	Central locking	Leather interior design
Air conditioning	Cruise Control	LED daytime running lights
Airbag - driver	Electric heated seats	LED headlights
Airbag passenger	Electric mirrors	Light sensor
Alloy Wheels	Electric side mirrors	Panoramic roof
Android Auto	Electric windows	Sunroof
Apple CarPlay	ESP	Tinted windows
Armrest	Full-LED headlights	Trekhaak
Automatic climate control, 2 zones	Immobilizer	Tyre pressure monitoring
Bluetooth		

Info

***ENGINE DOESN'T START - ACCIDENT NOT REGISTERED IN INSURANCE.